



SERVICE PARTS LIST

BULLETIN NO.
54-49-1020

SPECIFY CATALOG NO. AND SERIAL NO. WHEN ORDERING PARTS		REVISED BULLETIN	DATE
HAMMER TACKER			Jan. 2015
CATALOG NO.	48-22-1020	WIRING INSTRUCTION	
	SERIAL NUMBER		

EXAMPLE:
Component Parts (Small #) Are Included
When Ordering The Assembly (Large #).




FIG.	PART NO.	DESCRIPTION OF PART
1	45-16-0110	Impact Shoe
2	-----	Front Cover
3	-----	Pan Head Phillips Threaded Pin
4	-----	Split Ring Lock Washer
5	-----	Nylok Hex Nut

NO. REQ.
(1)
(1)
(1)
(1)
(1)

FIG. 1,2 **NOTES**
Front Cover must be loosened or removed before replacing Impact Shoe.